


SAFETY RECALL

INTERMATIC DIGITAL TIMERS

MODEL DT17 (Includes DT17C and DT17C8)
DATE CODES 40Z to 52Z or ENDING A, B, or C



Distributed September 2005 to December 2008

The recalled timers can have a faulty ground connection, which can pose an electrical shock hazard.

The brand name, model number ("DT17") and affected date code (40Z to 52Z or ending in A, B, or C) can be located on the timer as shown above. If you have one of these timers, stop using it and contact Intermatic immediately:

www.intermatic.com

or

1-800-704-3595

Affected timers returned to Intermatic will be replaced, free of charge.

In cooperation with the U. S. Consumer Product Safety Commission

Post until June 30, 2009